

Site monitoring report

Please find detailed below the report for the site monitoring undertaken. If you should have any queries or require any photographs taken on the Elmstead Hall site, please do not hesitate to contact me.

Site Name: Elmstead Hall

File Ref: 14.421.39.2

Operator: David Hunter

Site Representative:	Joanna	Bradley	SRC	(JB).
----------------------	--------	---------	-----	-------

Visit also attended by	T Burns ((TB)	(ECC))
------------------------	-----------	------	-------	---

Visit no: 1 of 4

Date: 15/05/24

Time on site: 12:15

Time off site: 13:15

Monitoring Officer: T Burns Tel No: 03330136440

Site Co-ordinator: As above Tel No:

Permission no's:

ESS/105/21/TEN

Constraints:

- Weather: Dry/ Windy / Rain / Snow
- Noise (Officer perception) Acceptable/ Not acceptable / N/A -
- Approach roads: Dry / Dusty / Wet / Damp/Muddy / Flooded
- Ground: Combination of: Dry / Dusty / Wet / Damp / Muddy / Flooded
- Access: Obstructed / Not Obstructed / Mud on Road / Ice / Slippery
- Wheel cleaning: Washer / Spinner / Sweeper /none N/A
- Hose: In use / Not in Use / N/A

- Machinery: Working / Not working (Front loader in yard servicing processing plant and visiting HGV's; 1 no excavator, dumptruck and dozer in extraction area).
- In correct position: Yes / No / N/A
- Stockpiles: Height = Acceptable **see appraisal**
- Bunds: Profiled / Grassed / Weeds / NA

Actions from last site visit remain the same as from last monitoring visit:

- Condition 7 requires action. Update: No action.
- Condition 13 and 30 requires action each period/as notified. Update: Kept on as reminder.
- Separation of stockpiles from perimeter soil bunding. Update: One stockpile nearest entrance now infringing onto site perimeter bunding.
- Overburden/stockpiles heights to be monitored. Update: To be monitored by operator.

Inspection Results Summary:

- Site entrance with bellmouth showing tracking marks southwards along highway.
- Internal haul road in good condition.
- Perimeter mounds around site now infested with thistles.
- Lagoons on far western side now continue to have establishing vegetation both within and on perimeter banking.
- Lagoons in central area of site comprises principally two larger main water holding areas and one smaller to the west. Evidence of sand martin/rabbit holes in northern facing bank of unworked mineral.
- Excavations have now been completed within the eastern side of the footprint and excavations beginning to move westward.
- Backfilling along the eastern boundary started to provide buffer area of reservoir and to provide base for the clay lining.
- Sump on far eastern side partially filled with water.
- Central graded stockpile of overburden remains in place with further loose tipped overburden in piles placed above.
- Within processing plant area, plant producing gravel/stone product.
- Sand stockpile adjacent processing plant considerably down on previous visits.
- Central band of mineral remains to be worked.

Compliance with Conditions:

Permission/Condition No:7 Boundary Markers

Scope of Condition and Action to be taken: Operator required to peg out extraction areas and maintain pegs during site operating period.

Action to be taken by **Operator** or MPA/WPA:

Permission/Condition No:13 Topographical Surveys

Scope of Condition and Action to be taken: Surveys to be provided every 12 months.

Action to be taken by **Operator** or MPA/WPA:

Permission/Condition No:30 Noise Monitoring

Scope of Condition and Action to be taken: Operator required to submitted surveys on three monthly basis.

Action to be taken by **Operator** or MPA/WPA:

Permission/Condition No:53 Annual Report

Scope of Condition and Action to be taken: Operator to submit scheme when soils moved for restoration purposes.

Action to be taken by **Operator** or MPA/WPA

Permission under 2017 EIA regulations?:

• Yes / No

Actions to be taken before next site visit and carried over from last visit:

- Condition 7 requires action.
- Condition 13 and 30 requires action each period/as agreed.
- Overburden/stockpiles heights to be monitored.
- Ensuring highway cleanliness from material carry out/tracking marks.
- Pulling back stockpiles to avoid contamination of the perimeter mounds.

Date of next scheduled monitoring visit: 22nd August @ 12:15

Date of report: 16/05/24

Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.